


## **Section 3. Sustainable Management Criteria**

### **Santa Margarita Basin Groundwater Sustainability Plan**

#### **Appendix 3B Representative Monitoring Point Chemographs with Sustainable Management Criteria**


# Arsenic



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result


## Chloride



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result


## Chlorobenzene



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result


**DCE**



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result


## Iron



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result


# Manganese



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result

## MTBE




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result

## Nitrate





- Mount Hermon #2
- Measurable Objective
- Minimum Threshold

Aquifer: Lompico  
 TOC Elevation= 739.9 ft AMSL  
 Screenings= 290-300, 400-415, 430-460,  
 490-590, 600-725 ft bgs


#### Water Year Classification

- Critically Dry
- Dry
- Normal
- Wet

Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



- SVWD #3B
- Measurable Objective
- Minimum Threshold

Aquifer: Lompico, Butano  
 TOC Elevation= 672.47 ft AMSL  
 Screenings= 700-730, 880-1050, 1180-1370,  
 1400-1670 ft bgs


#### Water Year Classification

- Critically Dry
- Dry
- Normal
- Wet

Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




**PCE**



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result


**TCE**



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result


# TDS



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result




Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result






Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)


Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result



Square symbols indicate non-detects (ND)

ND are set at the state detection limits for purposes of reporting (DLR) (Title 22 §64400.34)

Measurable Objective set at DLR when Measurable Objective is non-detect. In wells with MO above MT, MT exceedance is not considered an Undesirable Result